or Refease 2000/04/17 CIA-RDP78B04767A000300070002-8 HANDLE VA CONTROL SYSTEM ONLY

> 25X1A -50456/67 18 December 1967

Copy 3

MEMORAHDUM FOR: Chief, Information Processing Division, NPIC

ATTENTION:

25X1A

THROUGH:

Chief, Technical Intelligence Division, NPIC

SUBJECT:

Type IV (118A) System Math Model

25X1A

- 1. The TID/SIEB has been performing measurements on the survey controlled range at ______ (imaged on Type IV camera system test missions) to determine the accuracy of the system math model (Model IV). The results have not been accurate because the final orientation matrix is in error.
- 2. To improve the orientation matrix a new approach has been formulated. The method is to apply the mirror reflection equation to determine the matrix M to replace the matrix M8 in Model 4. The attachment provides the mathematics for the new equations and two methods for determining IMC. Also included are some results of BIEB's test.
- 3. SIEB requests changes be made in Model 4 using Method 2 as outlined in the following attachment.

25X1A

Chief, Systems and Image Evaluation Branch, TID/NPIC

Attachment: Type IV (118A) System Math Model

Distribution:

cy 1 - NPIC/IPD, w/a

2 - NPIC/TID/SIEB, w/a

3 - NPIC/TID/SIEB, w/av

Excluded from Approved For Release dewngrading and

25X1A

declassification

∤1≱₹ċ√€1Æ-RDฅ₮₿₿₿4₮€7A00030007QQQ2_€8_{_∨≀A}

25X1A